



[www.thistlebond.com](http://www.thistlebond.com)


## PROJECT PROFILE

**PROJECT:** Conveyor Belt Repair  
**LOCATION:** Honduras


### THE PROBLEM

The conveyor belt carries stone from the quarry.

The stone carried on the conveyor belt had caused excessive damage. The '80' Durometer Paste Elastomer was used to carry out the repairs.



### THE SOLUTION



The damaged area was thoroughly abraded and all loose rubber was removed. The area was then primed followed by an application of our '80' Durometer Paste Elastomer with reinforcing tape.

This repair has been a complete success and has led to major repair business throughout the quarry.