



www.thistlebond.com

PROJECT PROFILE

PROJECT: Pump Refurbishments
LOCATION: Fiji Islands

THE PROBLEM

The pumps used by this processing company were in poor condition. The efficiency of their operation was now being affected and the pumps therefore required rebuilding or replacing.

Clearly the cost effective solution was to rebuild the pumps before their condition deteriorated to the level where they were beyond repair.



THE SOLUTION



The pumps were first blast cleaned and the corroded areas inside the pumps were rebuilt with our Ceramic Carbide Wearing Compound.

Once this had cured, the internal surfaces of the pumps were lined with two coats of the Super Low Friction Efficiency Coating.

The customer is delighted with the finish and performance and has adopted this system for all pump refurbishments.